

2019 PAVING

FINAL

*NOTE: Square yard quantities are estimates only. Contractor needs to do a physical inspection of area S.Y. quantities. Striping cost is incidental to the contract.

Island Wide Road Resurfacing

#	ROAD NAME	Recommended TREATMENT	2012 RSL	2015 RSL	2018 Current RSL	Calculated PCI	PCI Criteria	From Address.	To Address	Length Ft.	Width Ft	Area S.Y.	Treatment Cost	FAS NonFAS Local	Baseyard	Town / Subdivision	
GROUP # I HANAIEI ANAHOLA DISTRICT																	
1	KILAUEA RD	4" MF select repair areas Reconstruction	4	4	0	40	Road Failed damage vehicles	Kolo Rd	Titcomb St	2937	19	6200		FAS	Hanalei	Kīlauea	
2	S. ALIOMANU RD	2"MF w Repair Areas Reconstruction	4	0	0	40	Road Failed damage vehicles	Kūhiō Hwy	#4800 S 'Aliomanu Rd	5240	16	9316		NON-FAS	Hanalei	Anahola	
										8177							
	HANAIEI Anahola TOTAL										1.55	Miles	\$459,152.00				
GROUP # II KAPAA WAILUA DISTRICT																	
3	KAWAIHAU ROAD	2"MF w Repair Areas	0	0	0	40	Road Failed damage vehicles	Kūhiō Hwy	Mimilo Rd	2198	24+	6838		FAS	Kapa'a	Kawaihau Rd	
4	KAWAIHAU ROAD	3"MF w Repair Areas	0	0	0	40	Road Failed damage vehicles	Mimilo Rd	Nunu Rd+	1617	24	4752		FAS	Kapa'a	Kawaihau Rd	
5	KAWAIHAU ROAD	2"MF w Repair Areas	0	0	0	40	Road Failed damage vehicles	Nunu Rd+	Hauaala Rd	1093	30	3951		FAS	Kapa'a	Kawaihau Rd	
6	KAWAIHAU ROAD	Repair Areas 3" Thick M/F	8	8	4	50.2	Poor, no longer structurally sound	Hauaala Rd	Kahana Rd			1914		FAS	Kapa'a	Kawaihau Rd	
7	KAWAIHAU ROAD	Repair Areas 2" Thick M/F	8	8	4	50.2	Poor, no longer structurally sound	Hauaala Rd	Kahana Rd			587		FAS	Kapa'a	Kawaihau Rd	
8	KAULANA RD	2"MF w Repair Areas	4	0	0	40	Road Failed damage vehicles	Kiheī Rd	End	1409	16	2505		LOCAL	Kapa'a	Wailua Hselots	
9	KIHEI RD	2"MF w Repair Areas	4	0	0	40	Road Failed damage vehicles	Makani Rd	End	1331	16	2366		LOCAL	Kapa'a	Wailua Hselots	
10	HALEILIO ROAD	3"MF w Repair Areas	4	4	0	40	Road Failed damage vehicles	Kaulana Rd	Makani Rd	1675	16	2978		FAS	Kapa'a	Wailua Hselots	
11	MALA ST	2" MF Repair Areas at intersection with Kuamoo Road	8	8	0	40	Road Failed damage vehicles	Mala St Intersections w Kamalu on both sides		120		395		LOCAL	Kapa'a	Wailua Hmstds	
										9443							
	KAPA'A Wailua TOTAL										1.79	Miles	\$752,541.00				
GROUP # III KALĀHEO DISTRICT																	
12	PAPALINA RD	For distance of 251', lane on Golf Course side 6" Thick Mill and Fill and opposite lane 3" Thick Mill and Fill. Root removal areas between Kai Ikena Rd and Palama Rd will be 6" M&F with 2' deep biobarrier installed at Golf Course side EP and use ATB to fill root removal voids under pavement.	4	2	0	40	Road Failed damage vehicles	Near 4114 Papalina Rd	Kai Ikena Dr	251	36	1004		FAS	Hanapēpē	Kalaheo	

13	PAPALINA RD	For distance of 372', 6" Thick Mill and Fill for both lanes. For each of three areas where roots are bulging in the middle of the road, an area 4' wide by 28' long will be reconstructed to a depth of up to 24" depending on the condition of the root (2" State Mix 5 & 10" ATB plus up to 12" sub-base). 2' deep biobarrier installed at Golf Course side EP.	4	2	0	40	Road Failed damage vehicles	Near Kai Ikena Dr	Before Palama St	372	29	1199	FAS	Hanapēpē	Kalaheo
14	PAPALINA RD	3" Thick Mill and Fill 6' x 31' Area at intersection with Palama Rd	4	2	0	40	Road Failed damage vehicles	Intersection Palama Rd	Direction of Hwy	31	6	21	FAS	Hanapepe	Kalaheo
15	PAPALINA RD	3"MF w Repair Areas	4	2	0	40	Road Failed damage vehicles	Pala St to Start	End to Maka Rd	27	10	30	FAS	Hanapepe	Kalaheo
16	PAPALINA RD	3"MF w Repair Areas	4	2	0	40	Road Failed damage vehicles	Int of Maka Rd	Near Maka Teixeira Tract	564	20.10.4	373	FAS	Hanapepe	Kalaheo
17	PAPALINA RD	3"MF w Repair Areas	4	2	0	40	Road Failed damage vehicles	Maka Teixeira Tract	Before 4339 Papalina Rd	70	6	47	FAS	Hanapēpē	Kalaheo
18	PAPALINA RD	3"MF w Repair Areas	4	2	0	40	Road Failed damage vehicles	Maka Teixeira Tract	Before 4339 Papalina Rd	127	6	85	FAS	Hanapēpē	Kalaheo
19	PAPALINA RD	3"MF w Repair Areas	4	2	0	40	Road Failed damage vehicles	After 4339 Papalina Rd	About 4381 Papalina Rd	86	6	57	FAS	Hanapepe	Kalaheo
20	PAPALINA RD	3"MF w Repair Areas	4	2	0	40	Road Failed damage vehicles	About 4381 Papalina Rd	Puu Rd	188	12	251	FAS	Hanapepe	Kalaheo
21	PAPALINA RD	3"MF w Repair Areas	4	2	0	40	Road Failed damage vehicles	Puu Rde	Puu Rd	33	10	37	FAS	Hanapepe	Kalaheo
22	PAPALINA RD	3"MF w Repair Areas	4	2	0	40	Road Failed damage vehicles	Papalina Rd	Puu Red	41	43,18	158	FAS	Hanapepe	Kalaheo
										1790					
	KALaHEO TOTAL									0.34	Miles		\$211,759.00		
	GROUP #IV WAIMEA/KEKAHA DISTRICT														
23	MOI ROAD	2" MF Select Repair Areas Reconstruction	8	4	2	45.4	Very Poor, more potholes and cracking, worse ride	Ahi Rd	Alii Rd	1898	24	5061	FAS	Hanapēpē	Eleele
24	MOI ROAD	2" MF Select Repair Areas Reconstruction	8	4	2	45.4	Very Poor, more potholes and cracking, worse ride	Alii Rd	Hanapēpē Road	2129	24	5677	FAS	Hanapēpē	Eleele
25	NIELE RD	2"MF w Repair Areas Reconstruction	4	0	0	40	Road Failed damage vehicles	Waimea Canyon Dr	End	249	16	443	LOCAL	Hanapepe	Waimea
26	OIOI RD	2"MF w Repair Areas Reconstruction	4	0	0	40	Road Failed damage vehicles	End	Niele Rd	745	16	1324	LOCAL	Hanapepe	Waimea
27	MAULE RD	2"MF w Repair Areas Reconstruction	8	4	0	40	Road Failed damage vehicles	Waimea Canyon Dr	Haina Rd	1263	20	2807	LOCAL	Hanapepe	Waimea
28	ULILI RD	2"MF w Repair Areas Reconstruction	8	0	0	40	Road Failed damage vehicles	Keola St	Akialoa Rd	1753	20	3896	LOCAL	Hanapepe	Kekaha
										8037					
	Waimea/ Kekaha TOTAL									1.52	Miles		\$317,480.00		

PAVING GROUPS I TO IV TOTAL BASIC SUM BID (Items 1 through 28 INCLUSIVE)										5.20	Miles		\$1,740,932.00			
ADDITIVE/ALTERNATIVES																
AA GROUP # V																
AA-1	OLOHENA RD Mauka	3" MF Reconstruction	4	0	0	40	Road Failed damage vehicles	Kamalu Rd	#6011 Olohena	7066	18	2807	\$431,489.00	NON-FAS	Kapa'a	Wailua Hmstd.
										1.34	Miles					
AA GROUP # VI																
AA-2	KEALIA RD	2" OL Rehabilitation	6	5	5	56.5	Fair, noticeably bumpy ride	Kūhiō Hwy	Hopoe Rd	2541	25	7058	\$176,450.00	NON-FAS	Kapa'a	Kealia
										0.48	Miles					
AA GROUP # VII																
AA-3	HEKILI RD	2"MF w Repair Areas Reconstruction	8	6	5	56.5	Fair, noticeably bumpy ride	Hauaala Rd	Kawaihau Rd	2622	16	4661		LOCAL	Kapa'a	Kapa'a
AA-4	MALU RD	2"MF w Repair Areas Reconstruction	8	8	0	40	Road Failed damage vehicles	Olohena Rd	Apopo Rd	1514	22	3701		LOCAL	Kapa'a	Kapa'a
AA-5	APOPO RD	2" MF w Repair Areas	10	8	0	40	Road Failed damage vehicles	Malu Rd	Kanaele Rd	2328	22	5691		LOCAL	Kapa'a	Kapa'a
AA-6	OHU RD	2"MF w Repair Areas Reconstruction	10	8	5	56.5	Fair, noticeably bumpy ride	Hekili Rd	Hekili Rd	900	12	1200		LOCAL	Kapa'a	Kapa'a
AA-7	OPAEEKAA RD	2" MF 5'w #6108-Puuopae	10	4	2	40.6	Very Poor, more potholes and cracking, worse ride	Kamalu Rd	Puuopae	1800	5	1000		NON-FAS	Kapa'a	Wailua Hmstd.
AA-8	KAHOLALELE RD	2 " MF w 4" repair areas Reconstruction	6	4	2	40.6	Very Poor, more potholes and cracking, worse ride	Kuamoo Rd	end south near Hindu Monastery	1004	16	1785		LOCAL	Kapa'a	Wailua Hmstd.
										10168		\$464,809.00				
										1.93	Miles					
AA GROUP # VIII																
AA-9	HALENANI ST	2"MF w Repair Areas Reconstruction	6	6	4	50.2	Poor, no longer structurally sound	Kalena St	Kress St	302	30	1007		LOCAL	Kapa'a	Lihue Town
AA-10	WAA RD	2"MF w Repair Areas Reconstruction	8	6	5	56.5	Fair, noticeably bumpy ride	End	Rice St	1145	20	2544		LOCAL	Kapa'a	Lihue Town
AA-11	KALENA ST	2"MF w Repair Areas Reconstruction	6	6	4	50.2	Poor, no longer structurally sound	Kress St	Hoala St	306	30	1020		LOCAL	Kapa'a	Lihue Town
AA-12	KRESS ST	2"MF w Repair Areas Reconstruction	6	6	4	50.2	Poor, no longer structurally sound	Rice St	Kalena St	757	30	2523		LOCAL	Kapa'a	Lihue Town
										2510.00		\$153,929.00				
										0.48	Miles					
AA GROUP # IX																
AA-13	PUNEE RD	2"MF w Repair Areas Reconstruction	8	6	4	50.2	Poor, no longer structurally sound	End	End	3033	14	4718		LOCAL	Hanapepe	Omao

AA-14	WAILAAU RD	2"MF w Repair Areas Reconstruction	6	6	4	50.2	Poor, no longer structurally sound	Ala Kinoiki	past Waihoonou w areas near bridge	1458	18	2916		LOCAL	Hanapepe	Kōloa	
AA-15	ALOHA PL	2"MF w Repair Areas Reconstruction	20	14	5	56.5	Fair, noticeably bumpy ride	End	Wailau Rd	502	18	1004	837	LOCAL	Hanapepe	Kōloa	
AA-16	WAIHOONOU RD	2"MF w Repair Areas Reconstruction	20	20	6	67	Satisfactory, cracks & distress becoming visible	End	Wailau Rd	487	15	812		LOCAL	Hanapepe	Kōloa	
AA-17	HOKUA RD	2"MF w Repair Areas Reconstruction	10	8	4	50.2	Poor, no longer structurally sound	Kaunualii Hwy	Puu Rd	764	25	2122		LOCAL	Hanapepe	Kalaheo	
AA-18	POLARIS RD	2" OL Rehabilitation	10	10	8	76.6	Good, minor cracks	Maka Rd	Puu Rd	505	20	1122		LOCAL	Hanapepe	Kalaheo	
AA-19	PUU RD	2"MF w Repair Areas Reconstruction	8	4	3	50.2	Poor, no longer structurally sound	Hokua Rd	Papalina Rd	1580	10	1756		LOCAL	Hanapepe	Kalaheo	
AA-20	PUU KULANA PL	2"MF w Repair Areas Reconstruction	8	6	4	50.2	Poor, no longer structurally sound	End	Puu Rd	585	20	1300		LOCAL	Hanapepe	Kalaheo	
										8914.00							\$320,334.00
										1.69	Miles						
AA GROUP # X																	
AA-21	OMA RD	2"MF w Repair Areas Reconstruction	8	8	6	67	Satisfactory, cracks & distress becoming visible	Maule Rd	Oioi Rd	473	20	1051		LOCAL	Hanapepe	Waimea	
AA-22	HAINA RD	2"MF w Repair Areas Reconstruction	6	4	2	45.4	Very Poor, more potholes and cracking, worse ride	Waimea Canyon Dr	Maule Rd	1201	20	2669		LOCAL	Hanapepe	Waimea	
AA-23	HUAKAI RD	2"MF w Repair Areas Reconstruction	4	4	2	45.4	Very Poor, more potholes and cracking, worse ride	Waimea Canyon Dr	Makeke Rd	409	20	909		LOCAL	Hanapepe	Waimea	
AA-24	HAIKI RD	2"MF w Repair Areas Reconstruction	8	8	2	45.4	Very Poor, more potholes and cracking, worse ride	End	Makeke Rd	173	10	192		LOCAL	Hanapepe	Waimea	
AA-25	MAKEKE RD	2"MF w Repair Areas Reconstruction	6	0	0	40	Road Failed! damage vehicles	Kaunualii Hwy	Haina Rd	1657	20	3682		LOCAL	Hanapepe	Waimea	
										3913.00							\$200,526.00
										0.74	Miles						
AA GROUP # X																	
AA-26	IWIPOLENA RD	2"MF w Repair Areas Reconstruction	10	8	6	67	Satisfactory, cracks & distress becoming visible	Nukupuu St	Akialoa Rd	1343	20	2984		LOCAL	Hanapepe	Kekaha Resident Lots 4	
AA-27	ANIANIAU PL	2"MF w Repair Areas Reconstruction	6	6	4	50.2	Poor, no longer structurally sound	End	Kawailoa St	105	20	233		LOCAL	Hanapepe	Kekaha	
AA-28	NANAMUA ST	2"MF w Repair Areas Reconstruction	10	6	4	50.2	Poor, no longer structurally sound	End	Ulili Rd	1292	20	2871		LOCAL	Hanapepe	Kekaha	
AA-29	KAWAILOA ST	2"MF w Repair Areas Reconstruction	10	6	4	50.2	Poor, no longer structurally sound	End	End	2382	20	5293		LOCAL	Hanapepe	Kekaha	
AA-30	HOKUALA PL	2"MF w Repair Areas Reconstruction	8	6	4	50.2	Poor, no longer structurally sound	End	Kawailoa St	220	20	489		LOCAL	Hanapepe	Kekaha	
AA-31	HOKULELE PL	2"MF w Repair Areas Reconstruction	10	4	2	45.4	Very Poor, more potholes and cracking, worse ride	End	Kawailoa St	146	20	324		LOCAL	Hanapepe	Kekaha	
AA-32	KEOLA ST	2"MF w Repair Areas Reconstruction	8	6	4	50.2	Poor, no longer structurally sound	Ulili Rd	Nanamua St	1099	20	2442		LOCAL	Hanapepe	Kekaha	
										6587.00							\$278,874.00

										1.25	Miles						
ADDITIVE/ALTERNATIVES TOTAL										7.90	Miles		\$2,026,411.00				
TOTAL PAVING with Add/Alternatives Contractor: Maui Kuponu Builders, LLC										13.10	Miles		\$3,767,343.00				

Island Wide Crack Filling & Surface Sealing

#	ROAD NAME	Recommended TREATMENT	2012 RSL	2015 RSL	2018 Current RSL	Calculated PCI	PCI Criteria	From Address.	To Address	Length Ft.	Width Ft	Area S.Y.	Treatment Cost	FAS NonFAS Local	Baseyard	Town / Subdivision
CFSS Group #1 HANAIEI-Anahola																
1	MALAMAAINA PL	CFSS w Repair Areas	8	6	5	56.5	Fair, noticeably bumpy ride	End	End	759	16	1349		LOCAL	Hanaiei	Anahola Ag. Lots
2	KAMALOMALOO PL	CFSS w Repair Areas	10	10	8	76.6	Good, minor cracks	Hokualele Rd	Malama Aina Pl	1558	16	2770			Hanaiei	
3	HOKUALELE RD	CFSS w Repair Areas	8	8	6	67	Satisfactory, cracks & distress becoming visible	Kunio Hwy	Makai End	2122	18	4244		NON-FAS	Hanaiei	Anahola Ag. Lots I, II
										4439						
TOTAL CFSS Group #1 HANAIEI-Anahola										0.84	Miles	\$128,790.20				
CFSS Group #2 KAPA'A																
1	KAAO RD	CFSS w Repair Areas	10	6	5	56.5	Fair, noticeably bumpy ride	Keālia Rd	End	1534	16	2727		LOCAL	Kapa'a	Kealia
2	HOPOE RD	CFSS w Repair Areas	10	0	0	40	Road Failed! damage vehicles	Keālia Rd	End	348	14	541		LOCAL	Kapa'a	Kealia
3	KEAPANA RD	CFSS w Repair Areas	8	6	5	56.5	Fair, noticeably bumpy ride	Hauaala Rd	End	1316	12	1755		LOCAL	Kapa'a	Keālia Kapaa
4	MAKAMAKA ST	CFSS w Repair Areas	12	12	8	76.6	Good, minor cracks	Hauaala Rd	End	374	24	997		LOCAL	Kapa'a	Keālia Kapaa
5	AUKAKE PL	CFSS w Repair Areas	10	4	4	50.2	Poor, no longer structurally sound	End	Ohu Rd	125	20	278		LOCAL	Kapa'a	Kapaa, Ilima Gardens
6	HOLOMUA PL	CFSS w Repair Areas	8	6	5	56.5	Fair, noticeably bumpy ride	End	Ohu Rd	132	20	293		LOCAL	Kapa'a	Kapaa, Ilima Gardens
7	HAUOLI PL	CFSS w Repair Areas	10	6	5	56.5	Fair, noticeably bumpy ride	End	Ohu Rd	289	20	642		LOCAL	Kapa'a	Kapaa, Ilima Gardens
8	OHU RD	CFSS w Repair Areas	8	6	5	56.5	Fair, noticeably bumpy ride	Apelila St	Hekili Rd	1477	20	3282		LOCAL	Kapa'a	Kapaa, Ilima Gardens
										5595						
TOTAL CFSS Group #2 KAPA'A										1.06	Miles	\$138,368.79				
CFSS Group #3 LIHU'E																
1	KOKIO ST	CFSS w Repair Areas	8	6	5	56.5	Fair, noticeably bumpy ride	Pua Loke St	Pikake St	597	18	1194		LOCAL	Kapa'a	Lihue, Pua Loke,
2	ILIAHI ST	CFSS w Repair Areas	8	6	6	67	Satisfactory, cracks & distress becoming visible	Pua Loke St	Pikake St	457	18	914		LOCAL	Kapa'a	Lihue, Pua Loke,
3	PUAIKI ST	CFSS w Repair Areas	8	6	6	67	Satisfactory, cracks & distress becoming visible	Pua Loke St	Awapuhi St	297	20	660		LOCAL	Kapa'a	Lihue, Pua Loke,
4	PUA LOKE ST	CFSS w Repair Areas	8	6	6	67	Satisfactory, cracks & distress becoming visible	Haleko Rd	Pikake St	2286	24	6096		LOCAL	Kapa'a	Lihue, Pua Loke,
5	KUPU LN	CFSS w Repair Areas	14	8	7	67	Satisfactory, cracks & distress becoming visible	End	Pua Loke St	135	13	195		LOCAL	Kapa'a	Lihue, Pua Loke,

6	MOHALA ST	CFSS w Repair Areas	8	8	7	67	Satisfactory, cracks & distress becoming visible	Pua Loke St	Pikake St	356	15	593		LOCAL	Kapa'a	Lihue, Pua Loke,		
7	PIKAKE ST	CFSS w Repair Areas	8	8	7	67	Satisfactory, cracks & distress becoming visible	Nāwiliwili Rd	Pua Loke St	2266	18	4532		LOCAL	Kapa'a	Lihue, Pua Loke,		
TOTAL CFSS Group #3 LIHU'E										6394								
										1.21	Miles		\$254,862.00					
CFSS Group #4 KōLOA / KALāHEO																		
1	OHUOHU ST	CFSS w Repair Areas	12	8	7	67	Satisfactory, cracks & distress becoming visible	Waoke St	Wailau Rd	1535	20	3411		LOCAL	Hanapepe	Kōloa		
2	HOOLEI ST	CFSS w Repair Areas	14	12	9	87.7	Good, minor cracks	End	Ohuohu St	567	20	1260		LOCAL	Hanapepe	Koloa, Waikomo		
3	TAPA ST	CFSS w Repair Areas	14	10	8	76.6	Good, minor cracks	End	Ohuohu St	1817	20	4038		LOCAL	Hanapepe	Koloa, Waikomo		
4	MAKI ST	CFSS w Repair Areas	14	14	10	95.8	In very good condition	End	Ohuohu St	273	20	607		LOCAL	Hanapepe	Koloa, Waikomo		
5	OLONA ST	CFSS w Repair Areas	14	12	10	95.8	In very good condition	End	End	806	20	1791		LOCAL	Hanapepe	Koloa, Waikomo		
6	MAMAKI ST	CFSS w Repair Areas	10	8	8	76.6	Good, minor cracks	End	Waoke St	1873	20	4162		LOCAL	Hanapepe	Koloa, Waikomo		
7	MAMAKI PL	CFSS w Repair Areas	10	6	6	67	Satisfactory, cracks & distress becoming visible	End	Mamaki St	131	20	291		LOCAL	Hanapepe	Koloa, Waikomo		
8	PALAA PL	CFSS w Repair Areas	14	10	9	87.7	Good, minor cracks	End	Tapa St	262	20	582		LOCAL	Hanapepe	Koloa, Waikomo		
9	LOHE RD	CFSS w Repair Areas	6	6	5	56.5	Fair, noticeably bumpy ride	End	Waha Rd	1127	18	2254		LOCAL	Hanapepe	Kalāheo, Kukuioolono Est.		
10	KIKIWI RD	CFSS w Repair Areas	6	6	5	56.5	Fair, noticeably bumpy ride	End	Kikee Rd	320	18	640		LOCAL	Hanapepe	Kalāheo, Kukuioolono Est.		
11	KIKEE RD	CFSS w Repair Areas	6	6	5	56.5	Fair, noticeably bumpy ride	Lohe Rd	Waha Rd	1449	18	2898		LOCAL	Hanapepe	Kalāheo, Kukuioolono Est.		
12	AMI RD	CFSS w Repair Areas	6	6	5	56.5	Fair, noticeably bumpy ride	End	Kikee Rd	422	18	844		LOCAL	Hanapepe	Kalāheo, Kukuioolono Est.		
13	NANAKAI RD	CFSS w Repair Areas	14	10	9	87.7	Good, minor cracks	End	Waha Rd	779	18	1558		LOCAL	Hanapepe	Kalāheo, Kukuioolono Est.		
14	NANAKAI PL	CFSS w Repair Areas	10	10	9	87.7	Good, minor cracks	End	Nanakai Rd	147	18	294		LOCAL	Hanapepe	Kalāheo, Kukuioolono Est.		
										11508								
TOTAL CFSS Group #4 KōLOA / KALāHEO										2.18	Miles		\$349,253.40					
CFSS Group #5 WAIMEA / KEKAHA																		
1	ULILI RD	CFSS w Repair Areas	10	8	7	67	Satisfactory, cracks & distress becoming visible	End	Keola St	870	20	1933		LOCAL	Hanapepe	Kekaha		

2	NUKUPUU ST	CFSS w Repair Areas	14	14	10	95.8	In very good condition	Anianiau St	Iwipolena Rd	1151	20	2558		LOCAL	Hanapepe	Kekaha Resident Lots 4		
3	ANIANIAU ST	CFSS w Repair Areas	14	14	10	95.8	In very good condition	Ulili Rd	Nukupuu St	450	20	1000		LOCAL	Hanapepe	Kekaha Resident Lots 4		
4	AKIKI PL	CFSS w Repair Areas	12	12	10	95.8	In very good condition	End	Iwipolena Rd	358	20	796		LOCAL	Hanapepe	Kekaha		
5	IWIPOLENA RD	CFSS w Repair Areas	12	12	10	95.8	In very good condition	Akiki Pl	Nukupuu St	350	20	778		LOCAL	Hanapepe	Kekaha Resident Lots 4		
6	IWIPOLENA RD	CFSS w Repair Areas	12	12	10	95.8	In very good condition	End	Amakihi Rd	1181	20	2624		LOCAL	Hanapepe	Kekaha Resident Lots 4		
TOTAL										4360								
TOTAL CFSS Group #5 WAIMEA / KEKAHA										0.83	Miles		\$129,445.04					
TOTAL Crack Fill Surface Seal										Contractor : DMK & Associates, LLC			6.12	Miles		\$1,000,719.43		
GRAND TOTAL PAVING with Add/Alternatives and CRACK FILL SURFACE SEAL										19.21	Miles		\$4,768,062.43					

2019 IWRR Basic Bid		\$1,740,932.00		5.20	Miles	
2019 IWRR Additive/Alternatives		\$2,026,411.00		7.90	Miles	
2019 IWRR Basic Bid with Additive Alternatives		\$3,767,343.00		13.10	Miles	Contractor: Maui Kupon Builders, LLC
2019 IWCFFS		\$1,000,719.43		6.12	Miles	Contractor : DMK & Associates, LLC
GRAND TOTAL		\$4,768,062.43		19.22	Miles	